



# FRIMS Assam

## Flood Reporting And Information Management System



### Cumulative Flood Scenario of Cachar District from 02-Feb-2021 to 30-Dec-2021

Cumulative Flood Scenario from 02-Feb-2021 to 30-Dec-2021						
Particulars	Cumulative Flood Scenario from 02-Feb-2021 to 30-Dec-2021					
Name Of Revenue Circle Affected	Name of Flood Affected Revenue Circles			Name of Urban Flood Revenue Circles		
	Katigorah, Silchar			Silchar		
	Total :	2				
Villages Affected	Revenue Circle	No. of Villages	Name of Villages			
	Katigorah	25	Chandinagar Part – I, Dudpur Part – I, Dudpur Part – II, Dudpur Part – III, Gonirgram Part – II, Jagadishpur Part – I, Jagadishpur Part – II, Jagadishpur Part – III, Jagadishpur Part – V, Niz-Fulbari Part – III, Niz-Leverputa Part – I, Niz-Leverputa Part – II, Rangar Part – I, Rangar Part – II, Rangar Part – III, Saidpur Part – I, Saidpur Part – II, Saidpur Part – III, Sonapur Part – I, Sonapur Part – II, Sonapur Part – III, Tarinipur Part – III, Chandinagar Part – III, Chandpur Part – I, Chandpur Part – III			
	Silchar	21	Chibitabichia Part – III, Chibitabichia Part – IV, Chibitabichia Part – IX, Chibitabichia Part – V, Hiarbond Part – I, Hiarbond Part – II, Jaroiltola, Tapang Part – I, Tapang Part – II, Vitor Gangapur Part – II, Bagla Ghat Part – I, Bagla Ghat Part – II, Barsangan Grant, Chengcoorie Grant, Chengdwar Part – I, Chengdwar Part – II, Chengdwar Part – III, Kathal Grant, Merua Grant, Rosekandi Kabarikona Grant Part – II, Tarutajbari Part – II			
	Total	46				
Population And Crop Area Affected	Revenue Circle	Male	Female	Children	Total Population	Crop Area ( in Hect. )
	Katigorah	0	0	0	0	206
	Silchar	0	0	0	0	377
	Total	0	0	0	0	583
Relief Camps / Centres Opened	Nil					
Inmates In Relief Camps	Nil					
Human Lives Lost - Confirmed	Nil					
Human Lives Lost Confirmed - Death Type	Nil					
Human Lives Lost - Missing	Nil					
Animals Affected	Nil					
Animals Washed Away	Nil					
Houses Damaged	Nil					
Rescue Operation	Nil					
Relief Distributed	Nil					
Relief Distributed - Others	Nil					
Infrastructure Damaged - Embankment Breached	Nil					
Infrastructure Damaged - Embankment Affected	Revenue Circle	Number	Details			
	Lakhipur	2	Singirbond to SM Road at Hatirhar Singirbond   Hatirhar Singirbond   Dyke along L/B of River Borak from Singiebond to S.M Road at Hatirhar Singirbond, Length -900 M, Due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021, Restoration of damages on R/B of River Digli at Bahadurpur   Bahadurpur   Restoration of damages on R/B of River Digli at Bahadurpur length- 250 , Due to Sloughening/Erosion , as reported WRD Silchar on 06.09.2021			
	Silchar	8	Dyke Along with L/B of Borak from Masimpur to Kathakal   Ghagrapar   Dyke along L/B of Borak from Masimpur to Kathakal at Gangarpar, Lenght- 375 M, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021., Dyke along L/B of Borak from Masimpur to Kathakal   Berabak   Dyke along L/B of Borak from Masimpur to Kathakal, Berabak, Lenght- 320 M, due to Sloughening/ Erosion, as reported WRD Silchar on 06.09.2021., Dyke along R/B of River Borak from SLPWD road to Madhuramukh   Angarjur PH-II   Dyke along R/B of River Borak from SLPWD road to Madhura Angarjur PH-II, Lenght- 321 M, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021., Dyke along R/B of River Borak from SLPWD road to Madhuramukh   Karatigram, Rongpur   Dyke along R/B of River Borak from SLPWD road to Madhuramukh, Karatigram, Rongpur Lenght- 270 M, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021., Dyke along L/B of Borak from Uttarkrishnapur to Tarapur   New Colony Tarapur   Dyke along L/B of Borak from Uttarkrishnapur to Tarapur (Railway Gap-Portion) New Colony Tarapur, Lenght- 350 M, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021, Dyke Flood Embekment along L/B of Borak from Uttarkrshnpur   Stemerghat near Arjyapatty   Dyke Sloughening/Erosion, as reported WRD Silchar on 06.09.2021, R/B Madhura to Masimpur Dudhpatil   Dudhpatil pt-V   Dyke along R/B of River Borak from Madhuramukh to Massimpur at Dudhpatil-V Lenght- 315 M, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021, Dyke along L/B of Borak from Masimpur to Kathakal   Hatirhar   Dyke along L/B of Borak from Masimpur to Kathakal, Hatirhar, Lenght- 315 M, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021			

	Sonai	14	Breach like damage at patbari area near RK College Amraghat   Patbari Area Amraghat   Restoration of Breach like damage at patbari area near RK College Amraghat, Patbari Area Amraghat, due to Sloughening/Erosion Length- 285, as reported by WRD, Silchar, on dated 06.09.2021 , Dyke along L/B of River Sonai from S.M Road to Dharmikahl   Roypara Area on L/B of Sonai and R/B of Rukhni   Dyke along L/B of River Sonai from S.M Road to Dharmikahl, due to Sloughening/Erosion Length- 360, as reported by WRD, Silchar, on dated 06.09.2021 , Rukhni from Panibora to Bagabazar   Islamabad   Dyke along R/B of Rukni from Panibora to Bagabazar on L.B and Dulalgram to Tillanagar R/B due to Sloughening/Erosion Length- 200, as reported by WRD, Silchar, on dated 06.09.2021 , Rukni from Panibora to Bagabazar   Bongram   Dyke along B/B of Rukni from Panibora to Bhagabazar on L/B and Dulalgram to Tillanagar on R/B due to Sloughening/Erosion Length- 210, as reported by WRD, Silchar, on dated 06.09.2021 , L/B River sonai from SM Road to Dharmikhal   Pakoirpar Narsingpur Pt-III Area   Dyke along L/B of River sonai from S.M road to Dharmikhal (L/B of River Rukni) due to Sloughening/Erosion Length-200, as reported by WRD, Silchar, on dated 06.09.2021 , L/B Sonai from S.M Road to Dharmikhal (L/B of River Rukni)   Masjid (Ruknipaar Narsingpur Pt-III area)   Dyke along L/B of River Sonai from S.M Road to Dharmikhal (L/B of River Rukni) due to Sloughening/Erosion Length- 150, as reported by WRD, Silchar, on dated 06.09.2021 , Dyke along L/B of River Sonai from S.M Road to Dharmikhal   Suklayabaidya Basti   Dyke along L/B of River Sonai from S.M Road to Dharmikhal (L/B of Rukni) due to Sloughening/Erosion Length- 140, as reported by WRD, Silchar, on dated 06.09.2021 , Dyke along L/B of River Sonai from S.M Road to Dharmikhal   Nagdigram Pt-IV   Dyke along L/B of River Sonai from S.M Road to Dharmikhal due to Sloughening/Erosion Length- 140, as reported by WRD, Silchar, on dated 06.09.2021 ,
	Udharbond	1	Udharbond to Larsing approach of River Madhura to Tarapur   Gossapur Pt-III, Das Para near Kalimandir   Dyke along udharbond to larsing approach of River Madhura on its R/B length -300, due to Sloughening/Erosion, as reported WRD Silchar on 06.09.2021.
	<b>Total</b>	<b>25</b>	
<b>Infrastructure Damaged - Road</b>	<b>Revenue Circle</b>	<b>Number</b>	<b>Details</b>
	Katigora	6	Silchar Jaintia Road   Bihara Pt-III   Silchar Jaintia Road (Ch.200.00 M to Ch..61200.00 M) in stretches, due to incessant rainfall, as reported by Executive Engineer, PWRD Borkhola Katigora (T) Road division , on dated 31.08.2021. , Haritika to Salimabad   Chandinagar Pt-4   Haritika to Salimabad road (Approaches of RCC Bridge) eroded due to incessant rainfall, as reported by Executive Engineer, PWRD Borkhola Katigora (T) Road division , on dated 31.08.2021. , Bihara Pt-VI to SK Road   Bihara-Pt-VI   Bihara pt-Vi to S.K Road at Bihara (Approaches of RCC Bridge No 1/2 & 5/1 eroded due to incessant rainfall, as reported by Executive Engineer, PWRD Borkhola Katigora (T) Road division , on dated 31.08.2021. , Lakhirpur Boroitoli Road   Boroitoli Pt-II   Lakhirpur Boroitoli Road (Approches of RCC Bridge No.1/5,2/3 & 3/1) severely damage due to incessant rainfall, as reported by Executive Engineer, PWRD Borkhola Katigora (T) Road division , on dated 31.08.2021. , Haritika Salimabad Road   Haritika Salimabad, Katigora   Haritika Salimabad Road- (Ch.4700.00 M to Ch. 5400.00M To Ch.5700 to Ch..7900.00M) due to incessant rain on dated 03.09.2021, As reported EE PWD Borkhola & Katigora (T) Road Division., Katigora Harinagar Road to Koroikandi   Katigora   Katigora Harinagar Road to Koroikandi severely damaged due to heavy downpour last night from ch.3000 to ch.4000m in stretches, due to Rain as reported by PWD Borkhola & Katigora T Road Division, on dated 21.09.2021.
	Lakhipur	10	Binnakhandi Ghat   Binnakhandi Ghat, Lakhipur   Restoration of Road at Binnakhandi Ghat by Constructing RCC covered drain (L-300.00 M) of LRA Road under SDRF for the year 2021-22, As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, Road NH.53 Alney   Road NH-53 Alney , Lakhipur   Restoration of the Sliding stretch of Road NH=53 Alney TE From Ch.1150.00 M to Ch.1330.00 M Length -180.M, under SDRF for the year 2021-22, As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, Hawkipunjee   Hawkipunjee, Lakhipur   Restoration of Road from T02 to Hawkipunjee by Constructing RCC open Drain L-750.00 M under SDRF for the year 2021-22, As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, Dewan Bando Road   Dewan Bando Road, Lakhipur   Construction of RCC drain at Dewan Bando Road L-1000.00 M under SDRF for the year 2021-22, As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, US Labonkhal   US Labonkhal, Lakhipur   Restoration of Road From T03 to US Labonkhal by Constructing R.CC open drain L-700.00 M under SDRF for the year 2021-22, As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, Kalabil   Kalabil Lakhipur   restoration of Road at Kalabil by Constructing RCC Covered Drain L-400M of LRA road under under SDRF for the year 2021-22,As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, Amraghat Matinagar   Boali Grant   Restoration of Road portion of 200.00M length at Boali Grant of the Road Binnakhandi at L.R.A to Motingar Diderkush at Ch.2325 L-200 M under SDRF for the year 2021-22,As Reported by PWD Lakhipur Civil Sub-Division Territorial Road Division, Lakhipur dated 26.08.2021, Scotpur to Mazargram   Scotpur to Mazargram, Lakhipur   Construction of 6M Span Boz Cell Culvert & RCC Drain of the Road From Scoutpur to Mazargaram (6 M Culvert Scoutpur with RCC Drain Length
	Silchar	2	Itkhola Ghaniwala Road   Itkhola Silchar   Restoration of Itkhola Ghaniwala Road (Construction of 02 Nos. Slab Culvert and approaches of Slab Culvert Due to Rain as reported EE Engineer PWRD Silchar/Udharbond T Road Division on dated 01.06.2021., Chandmari Road (Kendriya Vidyalaya Road)   Chandmari Road   Restoration of Chandmari Road (Kendriya Vidyalaya Road)Construction of 01 No.Slab Culvert, Drain and Approches of Slab Culvert Due to Rain as reported EE Engineer PWRD Silchar/Udharbond T Road Division on dated 01.06.2021.
	Udharbond	3	Pangram Amranagar Road   Udharbond   Pangram Amranagar Road (Ch. 7670.00 M to Ch.7760.00M) as reported Executive Engineer PWD Silchar & Udharbond Territorial Road Division, Silchar on dated 19.08.2021., S.K Road To Khaspur   Udharbond   S.K Road to Bagerkona Via Dev Basti (Approch of Bridge No1/2) as reported Executive Engineer PWD Silchar & Udharbond Territorial Road Division, Silchar on dated 19.08.2021., Laisong Razabazar Road   Laisong Razabazar   Laisong Razabazar Road (Severe erosion occurred) Ch.20900.00 M to 20980.00M due to incessant Rain, as reported EE PWD Silchar Udharbond (T) Road Division on dated 30.08.2021.
	<b>Total</b>	<b>21</b>	
<b>Infrastructure Damaged - Bridge</b>	<b>Nil</b>		
<b>Infrastructure Damaged - Others</b>	<b>Revenue Circle</b>	<b>Wildlife affected under protected areas description</b>	<b>Other Details</b>

	Katigorah	Road Breaches   Due to incessant rainfall improper functioning of sluice gates and discharge of water from Baleshwar river breach occurred at a point in the Mahadevpur bus stand and Mahadevpur pt- I to Pt-II road under Katigorah Revenue Circle where 30M of area was washed away on 07.08.2021. Co-ordinates: N24°59'16.65" E092°27'04.43".
	Silchar	Road Breaches   1. Road From E&D point at Water Works Road to Bagadhar Via Bethukandi (Ch. 3500.00m to Ch. 4000.00 in streches Dated 29.06.2021 Nature of Damage -Erosion)due to Rain.
	Udharbond	Road Breaches   1. Kumarcherra Bazar NEC Road To Dhola Punjee To Kalinagar (Ch.120.00m to Ch.5100.00 in Streches Dated 29.06.2021 (Natie of Damage Erosion)due to Rain , Road Breaches   2. Harinagar Kumacherra NEC Road to lankar Punjee (Ch. 200.00m to Ch. 1800.00 in Streches Dated 29.06.2021 ) Nature of Damage -Erosion ,Hard Crust Damage. due to Rain , Road Breaches   3. Baladhan T.E to DIGLI Kashiapunjee Via U.S Diksa Balannagar and U.S Durganagar (Ch.200.00m to Ch.900.00 in Streches Date 29.06.2021 nature of Damage -Erosion) due to Rain , Road Breaches   4. Pangram Amaranagar Road (Ch.7310.00 m to Ch.7335.00 in Streches dated 29.06.2021 (Nature of Damage -Erosion) due to Rain , Elementary Schools Damaged   Damage of school building and urinal of 656 No.Dayapur Bazarghat LPS, Cluster-Dayapur under Udharbond Education Block due to erosion in river Madhura on 25/08/2021
Erosion	<b>Revenue Circle</b>	<b>Details</b>
	Katigorah	Kunapara under Katigorah Revenue Circle   Discharge of water from Larang River, Kalain has caused Erosion of 350mt. and 150 Mt. of lengths at two areas which are 500 mt. apart on dated 13.08.2021   0, 1. Mohadevpur 2.Santipur 3.Borjuarai 4.Mohadevpur   1. Mohadevpur- Immediate Measures for restoration of Flood damaged of Dyke along R/B of Borak from Gonigram to Katigorah due to Sluoghening as well as Erosion of River length- 400m on dated 4th July 2021, as reported by EE Cachar Inv W.R Division, Badarpur. Long-245037 Lat-923942 2. Santipur- Immediate measures for restoration of Flood Damaged of Dyke along R/B of Borak from Gonigram Katigorah due to Sluoghening as well as Erosion of River length- 400m on dated 4th July 2021, as reported by EE Cachar Inv W.R Division, Long-245048 Lat-923958. 3. Borjuarai- Immediate Measures for Restoration of Flood Damaged of Dyke Along R/B of Borak From Ganigram to Katigorah due to Sluoghening as well as Erosion of River length- 400m on dated 4th July 2021, as reported by EE Cachar Inv W.R Division, Badarpur. Long-245037 Lat-923942 4. Madarpur-Immediate measures for restoration of Flood damaged of Dyke along R/B of River Borak From Katigorah to Harinagar BOP Camp due to Sluoghening as well as Erosion of River length- 550 m on dated 4th July 2021, as reported by EE Cachar Inv W.R Division, Badarpur. Long-245252 Lat-923108 5. Kunapara TE- Immediate measures for restoration of Flood damaged from Kunapara T.E to Sindura IX PMGSY Road near River Larang due to Sluoghening as well as Erosion of River length- 100m on dated 4th July 2021, as reported by EE Cachar Inv W.R Division, Badarpur. Long- NIL, Lat-NIL   0
	Lakhipur	Jirighat Bahadurpur   Severe Erosion observed at the right Bank of Digli river near PWD Bridge No 4/1 of the Jirighat Bahadurpur Road, As reported by Executive Engineer Water Resource, Division Silchar. on 24.08.2021   0
	Silchar	Tarapur Pt-VII (Shibbari Road)   Erosion in Tarapur Pt-VII near Sinking area along the left bank of River Barak where 10 nos. of familes got affected yesterday i.e. on 21/06/2021. Erosion length is 100m (approx.)   0, Chutrasangkon village under Chesri GP, PS : Borkhola.   2(tow) numbers of dwelling houses are being damaged by continued land erosion in the bank of Barak River at Chutrasangkon village under Chesri GP, PS : Borkhola. The damaged location is at around 2(two) km. distance from Ranighat Bridge point towards Durgapur. Date of incident-3rd July, 2021 The houses of following persons being damaged to resulting homeless.1) Dwelling house of Smti. Rathi Rani Das.2) Dwelling house of Shri Sushil Das.   10
	Udharbond	Udharbond LAC   Road From Down Bandhu Road near Salamatpur to Thailu Colony Gultilla Via Bramanbasti to South Ladhuma (T01 to Langla Cherra) Package No-AS-03-163) (Ch. 2900.00 M to 3250.00 M in Streches) as reported by Executive Engineer PWD Silchar & Udharbond Territorial Road Division, Silchar on dated 18.08.2021.   0
Landslide	<b>Revenue Circle</b>	<b>Details</b>
	Udharbond	Pangram Amranagar   Pangram Amranagar Road (Ch.7670.00 M M to Ch.7760.00 M) As reported by Executive Engineer PWD Silchar & Udharbond Territorial Road Division, Silchar on dated 19.08.2021.   0
Urban Flood	<b>Revenue Circle</b>	<b>Details</b>
	Silchar	Linkroad, National Highway road point, Ambicapatty, Padma Nagar, Sonai Road, Shillongpatty, Church Road, Chandicharan Road, Chengcoorie Road, Punna Paul Road, Mondirdighirpar, Radamadhab park, Shyamananda Lane Janakpur, New Market, Fatak bazar   Due to incessant rainfall in the early morning today (on dated 21.07.2021) for around 5hrs these areas of Silchar Municipal Area got partially inundated due to water logging due to blockage of drain, encroachment over drain, garabage dumping over drains and improper drainage system.   0, Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road   Due to yesterday's rainfall at night partially inundated due to water logged.   0