

Cumulative Flood Scenario of Cachar District from 01-May-2023 to 31-Oct-2023						
Particulars	Cumulative Flood Scenario from 01-May-2023 to 31-Oct-2023					
Name Of Revenue Circle Affected	Name Of Flood Affected Revenue Circle					Name Of Urban Flood Revenue Circle
	Silchar					Silchar
	Total : 1					
Villages Affected	Revenue Circle	No. of Villages	Name of Villages			
	Silchar	2	Berenga Part – IV, Kanakpur Part – II			
	Total	2				
Population And Crop Area Affected	Revenue Circle	Male	Female	Children	Total Population	Crop Area (in Hect.)
	Silchar	250	225	90	565	0.00
	Total	250	225	90	565	0.00
Relief Camps / Centres Opened	Nil					
Inmates In Relief Camps	Nil					
Human Lives Lost - Confirmed	Nil					
Human Lives Lost Confirmed - Death Type	Nil					
Human Lives Lost - Missing	Nil					
Human Lives Lost Missing - Type	Nil					
Animals Affected	Nil					
Animals Washed Away	Nil					
Houses Damaged	Nil					
Rescue Operation	Nil					
Relief Distributed	Nil					
Relief Distributed Others	Nil					
Infrastructure Damaged -	Revenue Circle	Number	Details			

Embankment Breached	Sonai	15	<p>Dyke along B/B of river Rukni from Paniborah to Baghabazar Islamabad Dyke along B/B of river Rukni from Paniborah to Baghabazar to Baghabazar and Dulalgram to Tillanagar, Length of damage 180m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.324320, Lat - 92.506405, Dept - Water Resource Deptt.),</p> <p>Dyke along B/B of river Rukni from Paniborah to Baghabazar Saptagram Dyke along B/B of river Rukni from Paniborah to Baghabazar to Baghabazar and Dulalgram to Tillanagar, Length of damage 150m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.552807, Lat - 92.837503, Dept - Water Resource Deptt.),</p> <p>Dyke along L/B of river Sonai from SM ROAD Bekirpar Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Rukni) Length of damage 100m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.375460, Lat - 92.511200, Dept - Water Resource Deptt.),</p> <p>Dyke along L/B of river Sonai from SM ROAD Pakoirpar Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Rukni) Length of damage 120m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.650395, Lat - 92.864326, Dept - Water Resource Deptt.),</p> <p>Dyke along L/B of river Sonai from SM ROAD Gandhinagar Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Rukni) Length of damage 150m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.652760, Lat - 92.866350, Dept - Water Resource Deptt.),</p> <p>Dyke along L/B of river Sonai from SM ROAD Ruknipar Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Rukni) Length of damage 200m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.656934, Lat - 92.868075, Dept - Water Resource Deptt.),</p> <p>Dyke along L/B of river Sonai from SM ROAD Julonpool Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Rukni) Length of damage 100m as per report received from Assistant</p>
---------------------	-------	----	--

Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 24.661121, Lat - 92.872591, Dept - Water Resource Deptt.),
 Dyke along L/B of river Sonai from SM ROAD TO Dharmikhal | Jamalpar | Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Sonai) Length of damage 300m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 24.631850, Lat - 92.909470, Dept - Water Resource Deptt.),
 Dyke along L/B of river Sonai from SM ROAD to Dharmikhal | Somabari Bazar | Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Sonai) Length of damage 150m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),
 Dyke along L/B of river Sonai from SM ROAD to Dharmikhal | Roypara | Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Sonai) Length of damage 350m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 24.659720, Lat - 92.879540, Dept - Water Resource Deptt.),
 Dyke along L/B of river Sonai from SM ROAD to Dharmikhal | Tulargram | Dyke along L/B of river Sonai from SM ROAD to Dharmikhal (L/B of of Sonai) Length of damage 350m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 24.722763, Lat - 92.888878, Dept - Water Resource Deptt.),
 Ringbund at village Jhangerbali on L/B | Jhangerbali-Tundarkandi | Ringbund at village Jhangerbali on L/B of Borak Length of damage 300m & 250m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 24.764896, Lat - 92.877749, Dept - Water Resource Deptt.),
 Ring at Village Tundarkandi | Tundarkandi | Ring at Village Tundarkandi Length of damage 200m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 | (Long - 24.747600, Lat - 92.876500, Dept - Water Resource Deptt.),
 Dyke along R/B of river Sonai from Palonghat | Bontarapur | Dyke along R/B of river Sonai from Palonghat to upwards Length of damage 150m as per report received from Assistant Executive Engineer

			Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 24.638378, Lat - 92.914050, Dept - Water Resource Deptt.), Dyke along R/B of river Borak from Sonaimukh to Modhuramukh Bagpur, Neirgram Dyke along R/B of river Borak from Sonaimukh to Modhuramukh Length of damge 900m as per report received from Assistant Executive Engineer Sonai-Dholai W.R Sub-Division, Sonai dated as on 19.07.2023 (Long - 27.773440, Lat - 92.870144, Dept - Water Resource Deptt.)
	Total	15	
Infrastructure Damaged - Embankments Affected	Nil		
Infrastructure Damaged - Road	Revenue Circle	Number	Details
	Silchar	33	Badri Bridge Approach Road Badripar Badri Bridge Approach Road have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), KASHIPUR BERENGA ROAD (BADRI BRIDGE APPROACH ROAD). KASHIPUR BERENGA KASHIPUR BERENGA ROAD (BADRI BRIDGE APPROACH ROAD) Length 1.600 As reported by EE PWD Silchar Road (T) Division on dated 17.06.2023. (Long - 24.812483, Lat - 92.855731, Dept - PWD (Roads)), S.F. ROAD. Silchar S.F. ROAD length 0.045 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. (Long - 24.819701, Lat - 92.806996, Dept - PWD (Roads)), MOTHER TERESA ROAD. Silchar MOTHER TERESA ROAD length 2.100 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. (Long - 24.820367, Lat - 92.730710, Dept - PWD (Roads)), MAHADEB BARI ROAD. MAHADEB BARI MAHADEB BARI ROAD Length-2.000 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. (Long - 24.812333, Lat - 92.810719, Dept - PWD (Roads)), NORMAL SCHOOL TO JAIL ROAD. NORMAL SCHOOL TO JAIL NORMAL SCHOOL TO JAIL ROAD Length- 0.910 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. (Long - 24.829180, Lat - 92.792796, Dept - PWD (Roads)), SHIBCOLONY ROAD. SHIBCOLONY

SHIBCOLONY ROAD Length 0.500 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.814133, Lat - 92.795547, Dept - PWD (Roads)),
SHYAMANANDA ASHRAM ROAD. | SHYAMANANDA ASHRAM | SHYAMANANDA ASHRAM ROAD Length-0.900 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.812079, Lat - 92.803375, Dept - PWD (Roads)),
GOPAL AKHRA ROAD. | GOPAL AKHRA | GOPAL AKHRA ROAD Length- 1.200 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.807943, Lat - 92.807273, Dept - PWD (Roads)),
D.C. OFFICE ROAD TO TREASURY OFFICE. | D.C. OFFICE | D.C. OFFICE ROAD TO TREASURY OFFICE Length- 0.140 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.829539, Lat - 92.803151, Dept - PWD (Roads)),
SILCHAR MUNICIPALITY OFFICE ROAD. | SILCHAR MUNICIPALITY OFFICE | SILCHAR MUNICIPALITY OFFICE ROAD Length-0.300 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.830931, Lat - 92.802182, Dept - PWD (Roads)),
BSNL OFFICE ROAD. | BSNL OFFICE | BSNL OFFICE ROAD Length-0.100 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.832652, Lat - 92.802391, Dept - PWD (Roads)),
N.M. GUPTA ROAD. | N.M. GUPTA ROAD | N.M. GUPTA ROAD Length-0.250 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.829220, Lat - 92.793100, Dept - PWD (Roads)),
DAS COLONY PANCHAYAT ROAD. | DAS COLONY | DAS COLONY PANCHAYAT ROAD Length 1.500 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.809474, Lat - 92.790709, Dept - PWD (Roads)),
S.H.ROAD C.R. AVENUE POINT TO CHIRUKANDI RAMNAGAR NH-37 POINT. | NH-37 POINT | S.H.ROAD C.R. AVENUE POINT TO CHIRUKANDI RAMNAGAR NH-37 POINT Length-4.330 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.805585, Lat - 92.794473, Dept - PWD (Roads)),
DOLOO MOINERBOND ROAD CH. 15650.00M to 16950.00M. | DOLOO MOINERBOND | DOLOO MOINERBOND ROAD CH. 15650.00M to 16950.00M Length-1.300 As reported by EE PWD Silchar Road (T) Division on dated

19.06.2023. | (Long - 24.853228, Lat - 92.828098, Dept - PWD (Roads)),
 OLD LAKHIPUR ROAD NEAR RCC BRIDGE TO FERRYGHAT. | OLD LAKHIPUR ROAD | OLD LAKHIPUR ROAD NEAR RCC BRIDGE TO FERRYGHAT Length-0.210 As reported by EE PWD Silchar Road (T) Division on dated 19.06.2023. | (Long - 24.811194, Lat - 92.842145, Dept - PWD (Roads)),
 TARAPPAUR SHIBBARI ROAD. | TARAPPAUR SHIBBARI | TARAPPAUR SHIBBARI ROAD Length-0.180 As reported by EE PWD Silchar Road (T) Division on dated 21.06.2023. | (Long - 24.835781, Lat - 92.781127, Dept - PWD (Roads)),
 CHURCH ROAD 300.00M DAMAGED, 2 NOS DAMAGED CULVERT. | CHURCH ROAD | CHURCH ROAD 300.00M DAMAGED, 2 NOS DAMAGED CULVERT Length 0.680 As reported by EE PWD Silchar Road (T) Division on dated 21.06.2023. | (Long - 24.822419, Lat - 92.796155, Dept - PWD (Roads)),
 BERENGA BASHAN (BISHRAN) ROAD. | BERENGA BASHAN | BERENGA BASHAN (BISHRAN) ROAD Length-0.200 As reported by EE PWD Silchar Road (T) Division on dated 21.06.2023. | (Long - 24.811440, Lat - 92.842141, Dept - PWD (Roads)),
 L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar | Diglee Khasia Punjee | L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar Ch.850.00 m to Ch.1000.00m as reported by EE PWRD Silchar & Udharbond T Road Division on 17.08.2023. | (Long - 2491357.000000, Lat - 93.116750, Dept - PWD (Roads)),
 L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar | Diglee Khasia Punjee | L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar Ch.1600.00 m to Ch.1650.00m as reported by EE PWRD Silchar & Udharbond T Road Division on 17.08.2023. | (Long - 9311727.000000, Lat - 2490834.000000, Dept - PWD (Roads)),
 L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar | Diglee Khasia Punjee | L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar Ch.2600.00 m to Ch.2700.00m as reported by EE PWRD Silchar & Udharbond T Road Division on 17.08.2023. | (Long - 9310797.000000, Lat - 2489209.000000, Dept - PWD (Roads)),

		<p>L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar Diglee Khasia Punjee L025- Road from Baladhan TE Diglee Khasia Punjee via US Diksa Bhuban Nagar and Us Durganagar Ch.5080.00 m to Ch.5130.00m as reported by EE PWRD Silchar & Udharbond T Road Division on 17.08.2023. (Long - 9310781.000000, Lat - 2488854.000000, Dept - PWD (Roads)), Amaranagar to Indranagar Amaranagar to Indranagar Amaranagar to Indranagar Road, Culvert at Ch.1710.00 and Approaches washed out causing a Breach of Length about 30 Miter. due to incessant Rain, As reported by Executive Engineer PWRD Silchar & Udharbond (T) Road Division, Silchar on dated 24/08/2023. (Long - 92.866413, Lat - 24.980955, Dept - PWD (Roads))</p>
Sonai	2	<p>Bantarapur Telephone exchange to Palonghat Bridge Sundari Bantarapur Telephone exchange to Palonghat Bridge at Sundari via Golasina. A stretch of 60 M (Width 3.5m including hard crust and shoulder at chainage 1700 M Damaged badly due to sinking of embankment adjacent to Rukni river at Sundari under sonai Revenue circle, as per report received from PWRD, Dholai & Sonai (T) Roads division, Dholai, as on dated 27.07.2023 (Long - 92.913992, Lat - 24.638395, Dept - PWD (Roads)), Bantarapur Telephone exchange to Palonghat Bridge at Sundari via Golasina Bantarapur BANTARAPUR TELEPHONE EXCHANGE TO PALONGHAT RCC BRIDGE AT SUNDARI VIA A length 60.00 m and width 3.5 m (including shoulder and hard crust), at ch. 1700.00 m, under Sonai Revenue Circle has been badly damaged due to sinking of embankment as the water of Rukni River flowing adjacent to the road started receding, as per report received from PWRD, Dholai & Sonai(T) Roads division, Dholai, as on dated 27.07.2023 (Long - 92.914260, Lat - 24.638419, Dept - PWD (Roads))</p>
Udharbond	16	<p>T-01 TO BHOLA PUNJEE BHOLA PUNJEE T-01 TO BHOLA PUNJEE AT CH. 500.00M. CH. 700.00M, CH. 4300.00M & CH.4500.00M (PKG. NO. AS-03-164) IN STRETCHES road have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), PAILAPOOL KUMARCHERRA NEC ROAD TO LANKAR PUNJI ROAD PAILAPOOL KUMARCHERRA PAILAPOOL KUMARCHERRA NEC ROAD TO LANKAR</p>

PUNJI ROAD (PKG. NO. AS-03-110) IN STRETCHES have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), S.K. ROAD TO KULICHERRA | KULICHERRA | S.K. ROAD TO KULICHERRA AT 4TH KM. have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), TIKALPAR ONGC POINT TO BAMDOO TE VIA KUMBHA AND ENDOGRAM | TIKALPAR | TIKALPAR ONGC POINT TO BAMDOO TE VIA KUMBHA AND ENDOGRAM AT CH. 500.00M. CH. 600.00M PKG. NO. AS-03-269 have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), DUMURGHAT GUABARI ROAD | DUMURGHAT GUABARI | DUMURGHAT GUABARI ROAD (EROSIION AT APPROACH TO BR. NO. 4/2) have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), GHUNGOORBOND PAKURPAR ROAD | GHUNGOORBOND PAKURPAR | GHUNGOORBOND PAKURPAR ROAD (EROSIION AT APPROACH TO BR. NO. 2/3) have been submerged and damaged due to incessant rain for the last few days, as per report received from PWRD Silchar & Udharbond (T) Road Division, Dated 17.06.2023 | (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), DUMURGHAT GUABARI ROAD (EROSIION AT APPROACH TO BR. NO. 4/2). | DUMURGHAT GUABARI | DUMURGHAT GUABARI ROAD (EROSIION AT APPROACH TO BR. NO. 4/2) Length-0.040 As reported by EE PWD T Road Division on Dated 17.06.2023 | (Long - 24.923869, Lat - 92.912886, Dept - PWD (Roads)), JAGANNATH SINGLE COLLEGE ROAD. LENGTH = 1.95 KM. | JAGANNATH SINGLE COLLEGE | JAGANNATH SINGLE COLLEGE ROAD. LENGTH = 1.95 KM Length- 1.950 As reported by EE PWD T Road Division on Dated

19.06.2023 | (Long - 24.870537, Lat - 92.880428, Dept - PWD (Roads)),
LARSING BAGAN ROAD. LANDSLID OCCURRED AT. CH. 350.00M TO CH.675.00M IN STRETCHES. | LARSING BAGAN | LARSING BAGAN ROAD. LANDSLID OCCURRED AT. CH. 350.00M TO CH.675.00M IN STRETCHES Length-6.500 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.907767, Lat - 92.895464, Dept - PWD (Roads)),
NH-53 TO 5TH KM OF S.K. ROAD VIA MADHURAMUKH AND BAHADURPUR. LENGTH = 3.033 KM. | MADHURAMUKH AND BAHADURPUR | NH-53 TO 5TH KM OF S.K. ROAD VIA MADHURAMUKH AND BAHADURPUR. LENGTH = 3.033 KM. As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.847565, Lat - 92.845287, Dept - PWD (Roads)),
PURBA SALGANGA KALIMANDIR ROAD (LAND SLIDE AT 1ST KM). | PURBA SALGANGA KALIMANDIR | PURBA SALGANGA KALIMANDIR ROAD (LAND SLIDE AT 1ST KM) Length- 0.750 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.919459, Lat - 92.965147, Dept - PWD (Roads)),
SILCHAR KUMBHIRGRAM ROAD (VIP ROAD). | SILCHAR KUMBHIRGRAM | SILCHAR KUMBHIRGRAM ROAD (VIP ROAD) Length- 0.100 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.914355, Lat - 92.975144, Dept - PWD (Roads)),
PANGRAM AMARANAGAR ROAD. | PANGRAM AMARANAGAR | PANGRAM AMARANAGAR ROAD Length-0.510 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.933511, Lat - 92.906422, Dept - PWD (Roads)),
AMRANAGAR INDRANAGAR ROAD. | AMRANAGAR INDRANAGAR | AMRANAGAR INDRANAGAR ROAD. Length- 2.100 As reported by EE PWD T Road Division on Dated 19.06.2023 | (Long - 24.980945, Lat - 92.866427, Dept - PWD (Roads)),
UDHARBOND BANSKANDI (MDR) ROAD (CH. 3857.00M TO CH. 8951.20M) DAMAGED DUE TO RAIN. | UDHARBOND BANSKANDI (MDR) | UDHARBOND BANSKANDI (MDR) ROAD (CH. 3857.00M TO CH. 8951.20M) DAMAGED DUE TO RAIN Length-5.100 As reported by EE PWD T Road Division on Dated 19.06.2023. | (Long - 24.851481, Lat - 92.941477, Dept - PWD

		(Roads)), PANGRAM PHE POINT TO BLOCK H.Q. VIA PATHARIA (CH.150.00M TO CH. 2980.00M ERROSION BY RIVER MADHURA IN STRETCHES. PANGRAM , PATHARIA PANGRAM PHE POINT TO BLOCK H.Q. VIA PATHARIA (CH.150.00M TO CH. 2980.00M ERROSION BY RIVER MADHURA IN STRETCHES Length-3.230 As reported by EE PWD T Road Division on Dated 19.06.2023. (Long - 24.885219, Lat - 92.891672, Dept - PWD (Roads))
	Total	51
Infrastructure Damaged - Bridge	Nil	
Infrastructure Damaged - Wildlife	Nil	
Infrastructure Damaged - Others	Nil	
Erosion	Revenue Circle	Details
	Katigorah	Kunapara T.E. to Sindura XI As reported by PWD Borkhola- Katigorah (T) Road Division and as per field inspection by Circle Officer Katigorah Revenue Circle along with Field Officer (DM) and AEE, CID (W.R) Div. Badarpur, it was observed that the Kunapara T.E. to Sindura XI PMGSY road is under the severe threat of erosion because of river larang which is flowing adjacent to it. An area of 250 mts (approx) has been severely eroding and if it continues the road connectivity will be closed. Severe erosion has been observed at the stretch since 01.07.2023 to still today i.e. 06.07.2023 15000 (Long - 24.583739, Lat - 92.321867), TRK Road to Sinjuripar (Govindapur Pt-II) severe erosion and land settlement has occurred at TRK Road to Sinjuripar (Govindapur Pt-II) Road due to flowing of river Harang and the meandering effect caused by Bonaimulla a channel of river Harang flowing adjacent to the said road. A Land measuring 350 Mts approx. has been eroded and settled as per field assessment and report received from PWRD Borkhola & Katigorah (T) Road Division on dated 11.10.2023. 12000 (Long - 24.893800, Lat - 926307.000000), Shivnaraynanpur Damaged due to Sloughening on GK Dyke at Shivnaraynpur area on the left Bank of River Banaimullah of length 150.00 M, as reported by Water Resource Department, CID Division, Badarpur on dated 17.10.2023. 0 (Long - 245235.270000, Lat - 923614.610000)
Landslide	Revenue Circle	Details
	Katigorah	Mohanpur Pt-II Dated: 20.05.2023 Due to incessant rainfall, a landslide has occurred in Mohanpur Pt-II under Katigorah Revenue Circle where the house of Ibal Uddin Sak has incurred damages. Detailed report will be submitted to DDMA, Cachar. as reported by CO katigorah on dated 20.05.2023 5 (Long - 24.898942, Lat - 92.588822),

		<p>Mohanpur Pt-II As per information received a landslide incident has occurred today at village Mohanpur Pt- II under Katigorah Revenue Circle where the houses of Montu Nath and Mintu Nath have incurred damages. as reported by Circle officer Katigorah on dated 25.05.2023 5 (Long - 92.588152, Lat - 24.901610), Talkar Grant A landslide due to incessant rainfall has occurred in Talkar Grant under Katigorah Revenue Circle on 14.06.2023 where the house of Boby Ghatowar has been affected 4 (Long - 92.524285, Lat - 24.982357)</p>
	Lakhipur	<p>Jhumtilla, Jirighat Landslide at Jhumtilla, Jirighat dated 20.06.2023, As reported by Sub-Divisional Engineer APDCL. 0 (Long - 93.107258, Lat - 24.807751)</p>
	Sonai	<p>Mohankhal Due to heavy rainfall from past few days an incident of landslide took place today morning (15/06/2023) in Mohankhal Village of Mohankhal-Rammaniukpur GP under Sonai Revenue Circle resulting in the partially damage of one Pucca house belongs to Matibur Rahman Mazumder S/o Mur Uddin Mazumder 5 (Long - 92.968381, Lat - 24.581718)</p>
	Revenue Circle	Details
Urban Flood	Silchar	<p>Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road, Sonai Road, Saratpally, Shillongpatty, Flash Flood due to excessive rainfall at Last night on dated 20.05.2023 400 (Long - 0.000000, Lat - 0.000000), National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road Flash flood in different places of Silchar Town due to heavy rainfall dated 12.06.2023. 15000 (Long - 0.000000, Lat - 0.000000), National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Flash Flood due to heavy rain fall on dated 14.06.2023, As reported by C.O Silchar Sadar Revenue Circle. 0 (Long - 0.000000, Lat - 0.000000), National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Charch Road, Bilpar Due to heavy rainfall flash flood occurred in different places of Silchar Town dated 15.06.2023 17000 (Long - 0.000000, Lat - 0.000000), National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Malinibeel, Bilpar, Nagatilla Flash flood due to heavy rain on dated 16.06.2023. As reported by Circle Officer Silchar Sadar. 0 (Long - 0.000000, Lat - 0.000000), National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Malinibeel, Bilpar, Nagatilla, Church Road, Flash Flood due to heavy rain on dated 17.06.2023. 20000 (Long - 0.000000, Lat - 0.000000), National Highway, Link Road, Ambicapatty, N.S. AVENUE, Sonai Road, Charch Road, Bilpar, Public School Road Due to heavy Rainfall & water logging Flash Flood have been occurred in different places of Silchar town, dated 18.06.2023 15000 (Long - 0.000000, Lat - 0.000000), Sonai Road Due to Rainfall & water logging Flash Flood have been occurred in Silchar town, dated 19.06.2023 1000 (Long - 0.000000, Lat - 0.000000), National Highway, Sonai road, Public School Road, flash flood</p>

	due to Heavy rain on dated 19.08.2023. 10000 (Long - 0.000000, Lat - 0.000000)
--	--

*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)